

Release note

8700AXL

FW version: 2.52.d11

New Features / Functions

1. Enhanced IPv6 performance.

Modifications & Bug Fixes:

1. Fixed E5573/E8372 hardware restart issue.
2. Fixed mail alert timing issue.
3. Fixed DNS display on Parental Control Provider.
4. Fixed NAT loopback issue under QoS setting.

✓ Notice:

New codebase! You must "Restart Device with Factory Default Settings" during Firmware Upgrade.

By default, "IPV6" and "Issue Router Advertisements" features have been disabled. Please enable them at Configuration > LAN > IPV6 Autoconfig for IPV6 connection.